

SELECTION TABLE OF TEMPERATURE, HUMIDITY, PRESSURE TRANSMITTERS Hxxxx



Industrial transmitters and regulators of Hxxxx family:

MEASURED VALUE / OUTPUT	2 x Relay	2 x Relay 4 x 4-20mA	2 x Relay 4 x 0-10V	2 x Relay RS485	2 x Relay RS232	2 x Relay Ethernet
temperature + 3 binary inputs		- from March	- from March	H0430 fig.2 page 64 H4431 fig.1 page 64	H4331 fig.1 page 64	H0530 fig.2 page 66 H4531 fig.1 page 66
temperature + humidity	H3060 fig.3 page 60 H3061 fig.5 page 60 H3020 fig.3 page 60 H3021 fig.5 page 60 H3023 fig.4 page 60	H3120 fig.3 page 62 H3121 fig.5 page 62	H3220 fig.3 page 62 H3221 fig.5 page 62			
temperature + humidity + 3 binary inputs				H3430 fig.3 page 64 H3431 fig.5 page 64 H3433 fig.4 page 64	H3331 fig.5 page 64	H3530 fig.3 page 66 H3531 fig.5 page 66
temperature + humidity + atmos. pressure		H7120 fig.3 page 62 H7121 fig.5 page 62	H7221 fig.5 page 62			
temperature + humidity + atmos. pressure + 3 binary inputs				H7430 fig.3 page 64 H7431 fig.5 page 64	H7331 fig.5 page 64	H7530 fig.3 page 66 H7531 fig.5 page 66

Hxxxx

