




# SELECTION TABLES OF TEMPERATURE, HUMIDITY, PRESSURE TRANSMITTERS

## INDUSTRIAL TRANSMITTERS of Txx1x, Pxxxx family:

| MEASURED VALUE / OUTPUT                   | 4 to 20mA             | 0 to 10V              | RS485                 | RS232                 | Ethernet              |
|---|-----------------------|-----------------------|-----------------------|-----------------------|-----------------------|
| temperature                               | P0120 figure 2 page27 |                       | T0410 figure 4 page39 | T0310 figure 4 page41 | P8510 figure 2 page33 |
|   | Px1x1 figure 1 page27 |                       | T4411 figure 3 page39 | T4311 figure 3 page41 | P85x1 figure 1 page33 |
|   | T0110 figure 4 page28 |                       |                       |                       | T0510 figure 4 page35 |
|   | T4111 figure 3 page28 |                       |                       |                       | T4511 figure 3 page37 |
| humidity                                  | T1110 figure 5 page28 |                       |                       |                       |                       |
| barometric pressure                       | T2114 figure 3 page30 | T2214 figure 3 page30 | T2414 figure 3 page39 | T2314 figure 3 page41 | T2514 figure 3 page37 |
| temperature+humidity                      | T3110 figure 5 page28 | T0210 figure 5 page31 | T3411 figure 5 page39 | T3311 figure 5 page41 | T3510 figure 5 page35 |
|   | T3113 figure 6 page28 | T0213 figure 6 page31 | T3413 figure 6 page39 |                       | T3511 figure 8 page37 |
|   | T3117 figure 7 page28 | T0211 figure 8 page31 | T3417 figure 7 page39 |                       |                       |
|   | T3111 figure 8 page28 |                       | T3419 figure 8 page39 |                       |                       |
| temperature+pressure                      |                       |                       | T5410 figure 4 page39 |                       |                       |
| temperature+humidity +barometric pressure |                       |                       | T7410 figure 5 page39 | T7310 figure 5 page41 | T7510 figure 5 page35 |
|   |                       |                       | T7411 figure 8 page39 | T7311 figure 8 page41 | T7511 figure 8 page37 |



## INTERIOR TRANSMITTERS of Txx18 family:

| MEASURED VALUE / OUTPUT                   | 4 to 20mA page 43 | 0 to 10V page 43 | RS485 page 45 | RS232 page 45 |
|---|-------------------|------------------|---------------|---------------|
| temperature                               | T0118             | T0218            | T0418         | T0318         |
| barometric pressure                       | T2118             | T2218            |               |               |
| temperature+humidity                      | T3118             | T3218            | T3418         | T3318         |
| temperature+humidity +barometric pressure |                   |                  | T7418         | T7318         |

